15176

PARCEL I.D. # 2235 451 004

AFFIDAVIT

This document is made and executed this 14th day of November, 2001, to inform concerned persons of a correction to the plat of the Lantern Hill at Willow Creek, a planned unit development, recorded as Entry No. 7452930 in Book 99-8P at Page 248. The corrections to the plat are as follows:

1. The distance between the monuments at the intersection of Danish Road and Scottish Drive to the next point of intersection monument at a bearing of South 58°07'29" West is 131.24 feet instead of 133.75 feet.

2. The intermediate distance between said monument at the intersection of Danish Road and Scottish Drive to the point of reverence to the point of curvature of Lot 1 is 53.68 feet instead of 56.19 feet.

3. The intermediate distance between said monuments at the intersection of Danish Road and Scottish Drive to the point of reference of the point of curvature on the south boundary line of said Lantern Hill at Willow Creek P.U.D. is 119.64 feet instead of 122.15 feet.

4. The bearing between the two most southwesterly monuments on Scottish Drive is North 38°00'24" East instead of North 55°27'04" East.

Items 1-3:

Item 4:

Tax I.D. No. 22-35-451-004

In witness whereof, I swear that the above change is correct and cause the same to be duly executed this 14th day of November, 2001.

Dale K. Bennett, P.E. & L.S.

(Seal: ENGINEER & LAND SURVEYOR — PROFE / DALE K. BENNETT 11-14-0)

STATE OF UTAH
                        :ss
COUNTY OF SALT LAKE

On this 14th day of November, 2001, personally appeared before me, Dale K. Bennett, signer of the foregoing instrument who duly acknowledged to me that they executed the same.

NOTARY PUBLIC

BK8550PG1655