

12951571
03/19/2019 11:57 AM \$142.00
Book - 10761 Pg - 6140
RASHELLE HOBBS
RECORDER, SALT LAKE COUNTY, UTAH
ENSIGN ENGINEERING
45 W 1000 S
SANDY UT 84070
BY: EAA, DEPUTY - WI 1 P.

AFFIDAVIT

STATE OF UTAH

COUNTY OF SALT LAKE


} ss

I, Karen F. White, holding License No. 191326, as a Land Surveyor in the State of Utah, being duly sworn hereby depose and say as follows:

- Ensign Engineering prepared a subdivision plat titled **Villages at Sandy Plat**, recorded August 15, 2017, as Entry No. 12596715, in Book 2017P, at Page 209 in the Office of the Salt Lake County Recorder.
- The Southwest Corner of Section 5, Township 3 South, Range 1 East, Salt Lake Base and Meridian is shown as a found brass cap monument. Said found monument is a Salt Lake County Street Monument located in the intersection of 9400 South and 700 East Streets.
- The Southwest Corner of Section 5, Township 3 South, Range 1 East, Salt Lake Base and Meridian is not set, but is of record being located South 29°33'10" East of the Salt Lake County Street Monument located in the intersection of 9400 South and 700 East Streets.
- The Basis of Bearing for the subdivision plat is between the Salt Lake County Street Monument located in the intersection of 9400 South and 700 East Streets and the South Quarter Corner of Section 5, Township 3 South, Range 1 East, Salt Lake Base and Meridian being South 89°12'10" East 2634.53 feet.
- The distance along the center line of Rose Cottage Way heading north of Oakhampton Drive labeled as N 2°54'17" W 98.67 on the plat is incorrect. The correct distance for this call should be 99.18'


I hereby state that this Affidavit has been prepared and signed by me, Karen F. White, for the purpose herein disclosed.


Karen F. White
License No. 191326


191326
KAREN F.
WHITE
3/19/19
STATE OF UTAH

Subscribed and sworn before me this 19th day of March, 2019.

My commission expires: March 25, 2022


Cherise Vincent

