

DISTANCE ON OUTSIDE NW'LY CORNER LOT I IN ERROR, S/B 53.483

Date 6/1/90

ENGINEERING
TH 2300 EAST SUITE 205

SHEET

90-7-86