After recording, return to:

Melissa Turchi, LUST Project Manager Utah Department of Environmental Quality Division of Environmental Response and Remediation 168 North 1950 West P. O. Box 144840 Salt Lake City, Utah 84114-4840

Recording requested by:

Dennis L. Harper, Real Estate Transaction Services Manager PacifiCorp 1407 West North Temple, Suite 320 Salt Lake City, Utah 84116 9399741
05/09/2005 11:37 AM \$22-00
Book - 9142 Ps - 7887-7893
GARY W. OTT
RECORDER, SALT LAKE COUNTY, UTAH
UTAH DEPARTMENT OF
BNUTRUMMENTAL QUALITY
PO BOX 144840
SLC UT 84114-4840
BY: SBM, DEPUTY - WI 7 P.

INSTITUTIONAL CONTROLS

Pursuant to the Utah Environmental Institutional Control Act (Utah Code Sections 19-10-101, et seq., PacifiCorp (sometimes referred to "Owner" herein), owner of the property located at 1407 West North Temple, in Salt Lake City, Salt Lake County, State of Utah ("Property"), Parcel No. 0834477004; more particularly described as:

COM AT SE COR SEC 34 T 1N R 1W SL MER W 36 RDS TO S LINE OF NORTH TEMPLE ST E 632.9 FT S 250 FT E 536 FT S 410 FT W 574.9 FT TO BEG 14.64 AC

hereby makes and imposes upon the Property the Institutional Controls below for the reasons and subject to the terms and conditions herein stated.

1. Institutional Controls are Necessary to Protect Public Health, Safety, Welfare or the Environment at the Property for the reasons described below.

During the course of its operation, the Salt Lake Automotive Center ("SLAC") on the Property utilized a 10,000-gallon gasoline and 1,000-gallon used oil underground storage tank (UST) (please refer to attached site maps). The gasoline tank was located near the front (northwest) corner of the building and was used to fuel company vehicles. The used oil tank was buried along the east side of the building near the southeast corner and was used to contain waste oil drained from company vehicles. The tanks were registered with Utah Department of Environmental Quality, Division of Environmental Response and Remediation (DERR) but have since been removed. The DERR has assigned Facility Identification Number 4001207 to this Property.

In 1986, the 10,000-gallon UST was removed from the northwest corner of the site adjacent to the SLAC building and no contamination was reported. In 1990, the 1,000-gallon used oil UST was removed from the southeast corner of the site adjacent to the SLAC building. Environmental samples contained RCRA-listed solvents and waste oil. In 1997, Utah Power over excavated contaminated soils around both former USTs and identified two separate releases. Contamination near the waste oil UST was associated with contamination from an adjacent abatement canal. The DERR considers this area of contamination a separate release unrelated to the gasoline UST and has assigned this release to its CERCLA Branch for management. The DERR-UST Branch is regulating the clean up of the release from the gasoline UST. The DERR has identified the release as "EGEI" in its files. Release EGEI was over-excavated to the extent practicable totaling approximately 1,348 tons of gasoline-contaminated soils that were excavated and transported off-site for disposal. Soil excavation was limited by the presence of buildings and utilities on-site. Residual soil and groundwater contamination were characterized and left on-site.

Based upon information currently available in the DERR's release file the DERR has determined that health and environmental risks arising from the contamination at the Property can be managed with institutional controls. Therefore, the DERR does not object to no further action being taken to address the characterized residual soil and groundwater contamination provided that the land use remains the same and that the institutional controls set forth below are followed.

Information about the contamination for Facility Identification Number 4001207; Release EGEI is available for public review in the files of the DERR at 168 North 1950 West, 1st Floor, Salt Lake City, Utah, 84116. The DERR contact person is currently Melissa Turchi, DERR project Manager, at (801) 536-4100.

2. The following Institutional Controls are imposed on the property:

a) Site Controlled Access

Access to the SLAC Site shall be limited to employees only through a security gate system located just west of the SLAC building. These gates may remain open during normal business hours to allow for parking and access to the main office and other buildings. The gates shall remain closed after hours with access being granted to only those employees with approved access. The Owner shall ensure that the gate is properly operated and maintained. In addition, the Owner shall ensure that the surface soil will be covered by asphalt, concrete, and/or buildings on the subject property to prevent dermal contact or ingestion of contaminated soils and/or groundwater (please refer to attached site map for location of residual contamination).

b) SLAC Building Ventilation

The Owner shall ensure ventilation of the SLAC building. The SLAC building is used to perform limited maintenance on vehicles and used to park vehicles during colder months. Residual contamination near the building may create contaminated vapors entering through the building floor. The Owner shall mitigate this potential hazard by ventilation of the building. The use of the building results in bay doors often being opened and closed providing ventilation to the building. In addition, a positive pressure ventilation fan is currently installed in the SLAC building for use during the winter months. The fan is window mounted introducing outside air into the building, which then escapes through vents in the ceiling and open doors. The fan is operated by an electronic timer to ensure ventilation in the building is provided throughout the day. The fan shall continue to be utilized daily during the winter months when bay doors and windows are not opened as frequently. It shall also be utilized in conjunction with open bays and windows during the summer months when employees are present in the building. The ventilation fan shall be included in the PacifiCorp "Preventive Maintenance Program for Critical Equipment" at the North Temple Complex and shall in accordance with that program receive the routine quarterly maintenance established for equipment critical to the safe and efficient daily operations of PacifiCorp facilities. In addition, all problems or concerns observed with the operation of the ventilation fan shall, at any time, be reported to the company maintenance program to ensure timely and effective repairs are made.

c) Limited Groundwater Use

The owner shall not use or allow anyone else to use on-site groundwater for any purpose.

d) PacifiCorp Environmental Remediation Company (PERCo) Oversight of Excavations On-Site

Owner shall ensure that excavation activities are overseen by environmental professionals and that 40-hr HAZWOPER trained personnel monitor construction workers to prevent unnecessary exposure to residual contamination at the SLAC Site (please refer to attached site map for location of residual contamination). PacifiCorp has established protocol for PERCo personnel to oversee all excavation activities performed at the Property to implement this institutional control. PERCo personnel are 40-hr HAZWOPER trained and shall provide the necessary services for construction worker oversight.

e) Public Notice of Residual Contamination

Owner shall post a public notice acknowledging the residual contamination, potential risks, and risk management in the SLAC building and shall also distribute guidelines to workers advising them of the risk and training them how to minimize exposure to residual contamination. A copy of this institutional controls document shall be stationed in plain sight within the SLAC building and with

facility personnel responsible for construction and maintenance activities at the subject property.

- The above described Institutional Controls run with the land and shall be operated and maintained in perpetuity unless terminated or modified as provided in Utah Code Section 19-10-105.
- The Executive Director of the Utah Department of Environmental Quality, or his/her designated representative, shall have access to the Property at all reasonable times to verify that this Institutional Control is being maintained and that the party or parties in possession of the Property are complying with the Institutional Control.
- These Institutional Controls may be enforced and/or protected as provided in Utah Code Section 19-10-106.
- These Institutional Controls may only be terminated in accordance with the provisions of Utah Code Section 19-10-105 and with the prior written approval of the Executive Director of the Utah Department of Environmental Quality.

EXECUTED as of the day of April

Dennis L. Harper Real Estate Transaction Services Manager

PacifiCorp

STATE OF UTAH

The foregoing instrument was acknowledged before me this 22 day of APOL , 2005 by Dennis L. Harper, the signer of said instrument.

	NOTARY PUBLIC KIM M. GARRICK 1483 GREENHIELD AVE SALT LAKE CITY, UT 84121
	MY COMMISSION EXPIRES MARCH 02: 2005 STATE OF UTAH

My Commission expires: 3/2/06

Dianne Nielson, Executive Director of the Utah Department of Environmental Quality, or his/her designated representative, hereby approves the foregoing Institutional Control pursuant to Utah Code Section 19-10-103.

Dianne Nielson Executive Director

Utah Department of Environmental Quality

STATE OF UTAH)

SS.

County of Salflake)


Subscribed and sworn to before me this and day of June, 2005, by Dianne Nielson, Executive Director of the Utah Department of Environmental Quality, or his/her designated representative.


Notary Public, residing at:

Kaipuille ut

My Commission expires: Wec - 15 2007







BK 9142 PG 7893