

WHEN RECORDED MAIL TO:

AFFIDAVIT OF CORRECTION

9813897
 08/16/2006 03:06 PM \$12.00
 Book - 9336 Pg - 7672-7673
 GARY W. OTT
 RECORDER, SALT LAKE COUNTY, UTAH
 DAVID MCKINNEY
 5151 S 900 S STE 200
 MURRAY UT 84117
 BY: LUG, DEPUTY - WI 2 P.

State of Utah)
 ss:
 County of Salt Lake)

The undersigned having been duly sworn, hereby deposes and says as follows:

1. I am a Professional Land Surveyor in the State of Utah, holding License Number 175754.
2. I acknowledge that an error exists in the centerline information of Heritage Farms Phase 3 Subdivision plat that is recorded at Salt Lake County Recorder's Office in the state of Utah.
3. I have reviewed the recorded plat and have found two errors in the intersection of Hayden Ridge Lane and Emery Forest Lane. The centerline call from monument to monument running North 45°13'34" East has a distance of "129.92" it should be "129.42". The second error is in Hayden Ridge Lane where the bearing is "South 44°33'01" East" it should be "South 44°46'26" East":

See Exhibit "A" attached hereto and by this reference made a part hereof. (See clouded area)

Dennis L. Bailey
 Dennis L. Bailey

SUBSCRIBED, SWORN AND ACKNOWLEDGED before me this 16th day of August, 2006.

Daryn D. Christensen
 NOTARY PUBLIC



