

SEWER LINE EASEMENT

0376424 Bk 0585 Pg 0307

RUSSELL SHIRTS & WASHINGTON CO RECORDER
1990 DEC 28 16:35 PM FEE \$0.00 BY KJP
REQUEST: IVINS TOWN

KNOW ALL MEN BY THESE PRESENTS:

In consideration of One Dollar (\$1.00) and other good and valuable consideration paid to ROMAN CATHOLIC BISHOP OF SALT LAKE CITY, a Corporation Sole, hereinafter referred to as "Grantor," by the City of St. George, City of Santa Clara, and the Town of Ivins, hereinafter referred to as "Grantees," Grantor does hereby grant, transfer and convey unto the Grantees both a temporary easement and a perpetual easement with the right to erect, construct, install and lay, and thereafter a perpetual easement to use, operate, inspect, repair, maintain, replace or expand sewer facilities, including but not limited to large diameter outfall lines, a service road, and possibly the placement of rip-rap, steel or concrete structures, under and along any portion of the property described herein which may be owned by Grantor in Washington County, State of Utah.

The temporary easement shall be 50 feet in width during the period of construction, and upon completion, the perpetual easement shall be 30 feet in width, the centerline of both the temporary and perpetual easements is described in Exhibit "A", attached hereto and incorporated herein by this reference.

Grantees agree to maintain the easement in good repair so that Grantor can continue to make such use of the surface of said easement as does not interfere with its purposes as described herein, and in such a manner that no damage results to the adjacent land of Grantor. Grantor shall provide reasonable ingress and egress to and from said right-of-way.

The benefits of this easement shall inure to the benefit of Grantees, or any municipal successor thereof, but shall not inure to or be for the benefit of any private assignee of Grantees.

The legal description of the property effected by the aforesaid Right-of-Way Easement is particularly described as follows:

The Easterly 1/3 of Lot 3, Block 28, ST. GEORGE AND SANTA CLARA BENCH IRRIGATION COMPANY SURVEY OF LANDS situated in Section 9, Township 42 South, Range 16 West, Salt Lake Base and Meridian, and as shown on the Official Map of said survey on file in the Office of the Recorder of Washington County, Utah.

TOGETHER WITH all improvements and appurtenances thereunto belonging, but being

I3/11/11

SUBJECT TO Easements, Restrictions and rights-of-way of record and those enforceable in law and equity.

LESS AND EXCEPTING all oil, gas and other mineral rights and rights thereto.

The undersigned covenants that it is the owner of the above-described property.

IN WITNESS WHEREOF, the Grantor has executed this instrument this 7th day of September, 1990.

GRANTOR:

ROMAN CATHOLIC BISHOP OF
SALT LAKE CITY, a Corporation
Sole

By: *Wm. K. Weigand*
Its: Encumbent Bishop

STATE OF UTAH)
) ss.
COUNTY OF SALT LAKE)

On the 7th day of September, 1990, personally appeared before me William K. Weigand, who being by me duly sworn did say that he is the Encumbent Bishop of Roman Catholic Bishop of Salt Lake City, a Corporation Sole, that the within and foregoing instrument was signed on behalf of said Corporation.

My Commission Expires:
October 27, 1992

Helene J. Mileski
Notary Public
Residing In:
Salt Lake City, Utah





BUSH & GUDGELL, INC.
Engineers • Planners • Surveyors
205 East Tabernacle
St. George, Utah 84770
(801) 673-2357

**Legal Description
Prepared For
Ivins, Santa Clara & St. George Sewer
Exhibit "A"**

Beginning at a manhole located within the right of way of 800 South Street Extended of Ivins, Utah, said point being located N 88°07'39" E 281.50 feet along the section line and North 4.47 feet from the South 1/4 corner of Section 5, Township 42 South, Range 16 West, Salt Lake Base and Meridian and running thence S 53°06' E 1200.00 feet more or less to a manhole; thence S 61°06' E 400.00 feet more or less to a manhole; thence S 71°08' E 400.00 feet more or less to a manhole; thence S 66°10' E 400.00 feet more or less to a manhole; thence S 42°40' E 400.00 feet more or less to a manhole; thence S 61°48' E 68.00 feet to a point on the West line of Section 9, Township 42 South, Range 16 West, said point being located N 0°40'46" W along the section line 1077.76 feet from the West 1/4 corner of said Section 9; thence S 61°48' E 332.00 feet more or less to a manhole; thence S 45°54' E 375.00 feet more or less to a manhole; thence S 37°17'26" E 400.00 feet more or less to a manhole; thence S 66°50'47" E 330.00 feet more or less to a manhole; thence S 41°05' E 330.00 feet more or less to a manhole; thence S 48°45' E 630.00 feet more or less to a manhole; thence S 26°10' E 220.00 feet more or less to a manhole; thence S 75°30' E 155.00 feet more or less to a manhole; thence S 32°49' E 320.00 feet more or less to a manhole; thence S 52°08' E 400.00 feet more or less to a manhole; thence S 44°40' E 400.00 feet more or less to a manhole; thence S 25°57' E 800.00 feet more or less to a manhole; thence S 42°36' E 400.00 feet more or less to a manhole; thence S 61°25' E 400.00 feet more or less to a manhole; thence S 69°01' E 5.59 feet more or less to a point on the South line of said Section 9, said point being located N 89°12'22" E along the section line 1038.85 feet from the South 1/4 corner of said Section 9; thence S 69°01' E 394.41 feet more or less to a manhole; thence S 69°01' E 305.00 feet more or less to a manhole; thence S 48°47' E 695.00 feet more or less to a manhole; thence S 47°46' E 370.00 feet more or less to a manhole; thence East 185.00 feet more or less to a manhole, said point also being located S 0°16'24" E along the section line 983.61 feet from the section corner common to Sections 9, 10, 15 and 16, Township 42 South, Range 16 West; thence S 45°30' E 400.00 feet more or less to a manhole; thence S 61°00' E 200.00 feet more or less to a manhole; thence S 47°57' E 175.00 feet more or less to a manhole; thence S 11°50' E 140.00 feet more or less to a manhole; thence S 44°05' E 165.00 feet more or less to a manhole; thence S 19°46' E 400.00 feet more or less to a manhole; thence S 43°24' E 240.00 feet more or less to a manhole; thence S 21°26' E 210.00 feet more or less to a manhole; thence S 5°29' W 154.87 feet to a point on the center section line of Section 15, said point being located N 89°36'10" E along the center section line 1088.14 feet from the West 1/4 corner of said Section 15; thence S 5°29' W 245.13 feet more or less to a manhole; thence S 4°20' W 320.00 feet more or less to a manhole; thence S 11°36' E 400.00 feet more or less to a manhole; thence S 82°00' E 345.00 feet more or less to a manhole; thence S 82°00' E 175.00 feet more or less to a manhole; thence S 34°45' E 400.00 feet more or less to a

manhole; thence S 34°45' E 390.00 feet more or less to a manhole; thence S 21°03' W 470.00 feet more or less to a manhole, said point being located in the highway right of way of old Highway 91, also known as Sunset Boulevard; thence S 5°15' E within said highway 70.00 feet more or less to a manhole; thence S 70°36' E within said highway 836.67 feet to a point on the center section line of Section 15, Township 42 South, Range 16 West, said point being located N 0°10'13" W along the center section line, 204.25 feet from the South 1/4 corner of said Section 15; thence S 70°36' E along said highway 173.33 feet more or less to a manhole; thence S 18°40' E 152.39 feet to a point on the south section line of said Section 15, said point being located N 89°22'33" E along the section line 211.67 feet from the South 1/4 corner of said Section 15; thence S 18°40' E 247.61 feet more or less to a manhole; thence S 22°27' E 400.00 feet more or less to a manhole; thence S 57°22' E 395.00 feet more or less to a manhole; thence S 2°30' E 650.00 feet more or less to a manhole; thence S 46°47'38" E 150.00 feet more or less to a manhole; thence S 11°00' W 385.00 feet more or less to a manhole; thence S 4°54' E 400.00 feet more or less to a manhole; thence S 4°54' E 295.00 feet more or less to a manhole; thence S 0°42' W 4.62 feet more or less to a point on the center section line of Section 22, Township 42 South, Range 16 West, said point being located N 89°21'38" E along the center section line 861.79 feet from the center 1/4 of said Section 22; thence S 0°42' W 295.38 feet more or less to a manhole; thence S 15°47' E 265.00 feet more or less to a manhole; thence S 50°20' E 360.00 feet more or less to a manhole; thence S 23°30' E 350.00 feet more or less to a manhole; thence S 23°30' E 320.00 feet more or less to a manhole; thence S 21°40' W 360.00 feet more or less to a manhole; thence S 50°22' W 175.00 feet more or less to a manhole; thence S 24°57' W 400.00 feet more or less to a manhole; thence S 1°00' E 82.00 feet more or less to a manhole, said point being on the centerline of the existing lower Santa Clara outfall sewer line, said point also being located N 89°32'12" E along the section line 1001.83 feet and North 377.26 feet from the South 1/4 corner of Section 22, Township 42 South, Range 16 West, Salt Lake Base and Meridian, said point being the terminal point of this easement.

5-4477

JRI/g